


# DO Cable Designator Instructions


pH Cable Designator	Connector Designator	Length	Cable Types	Length and Connector
A X - 5 0 0 0	- X X	□	X	X X X X

**FOR D4 ONLY**  
To order a  
BOOT use a  
1




**IMPORTANT**  
Use this sign **—** to indicate **FEET**  
Use a this sign **/** to indicate **INCHES**

## Connector Types




**D4**

4-Pin Circular  
Connector for  
DO Sensor




**FF**

Crimped Ferrules  
on Any Number  
of Leads



**L6**


5 Pin Lemo  
Cable Plug (Small)



**L7**

5 Pin Lemo  
Panel Mount Jack

## Wire and Cable Types



**D**  
GRAY DO CABLE  
COAX WITH TC LEADS  
AND OUTER SHIELD